

REPAIR DETAILS

Yard: Damen Shiprepair Amsterdam
Facility: Dry Dock N° 4

DRY DOCK LENGTH FACTS



**MAGELLAN
CRUISE VESSEL**

 **REPAIR &
MAINTENANCE**

 **TWO WEEKS
OF EXTENSIVE WORKS**

MAINTENANCE & SERVICE TO

16
LIFEBOATS



CHEMICALLY
CLEANED



The hull, rudders and propellers were thoroughly inspected, cleaned and polished



The high elastic friction clutch e-motor was overhauled



Significant steel repairs

